LOCKHEED AIRCRAFT CORPORATION DATE 3-26-62		ENGINEERING STUDY CHANGE PROPOSAL			N. A. C - 124		
		AFFECTS:	WSPC	x	PR	OJECT [<u> </u>
NAME OF MAJOR COMPONE F-2 FOIL	NT PART O	R LOWEST SUI			PART NO. 8		OR TYPE
TITLE OF PROPOSAL:	FOIL IMPRO	VENENTS					
NATURE OF PROPOSAL:							
· SE	PAGE 2			· : •	z.		:
*			•				•
	7						· •
REASON FOR PROPOSAL:				· · · · · · ·			
				-	-		
ESTIMATED COST AND ADDITIONAL FUNDING		D:					
ESTIMATED COST FOR ADDITIONAL FUNDING			_	TH CUS	Tomers - 8	SEE PAGE	3
TEMS AFFECTED BY PROPOSA	L:						•
SAFETY MISSION PERFORM- EFFEC. TIVENESS	OPERATING INT PROCEDURE CHAP ABIL	IGE- WEIGHT &	SUPPORT	MAINTE- NANCE PROCEDUR	SERVICE LIFE	FLIGHT MANUAL	MAINTE- BONAN JAUNAN
ST. MAN/HRS. REQ'D. TO AC	COMPUSIT CITY) L		<u> </u>		[X]	X
OURCE OF PARTS FOR KIT	COMPLISH CHA		AILABILITY _	PAGE 3	`	TER APPRO)VAL
DISPOSITION OF SPARES AFFE	CTED						
F344 PAWL - OF			•				

NATURE OF PROPOSAL

- I. To IRAN all F-2 Foils and modify them to provide:
 - 1. Pilot control over raising, lowering, and advancing of records.
 - 2. A mechanical down stop to accurately position the record in the duct.
 - 3. A new pawl which will mechanically index a single record at each actuation (this will eliminate record skipping). This pawl is currently being incorporated in all new F-2 foils.
 - 4. Reduced seal interference, by replacing the aft inflatable seal with a fixed hard faced seal.
 - 5. Smoother transport of records by modifying the pusher assembly to get better metering of the damping fluid.
 - 6. A simplified actuator change by adding a connector to the actuator leads for both the door and the record actuator.
 - 7. A new control panel which is compatable with the revised system.
 - 8. In the process of this rework, the F357-2 hatches will receive an IRAN.
- II. No Service Bulletin required. All work to be done at the factory per a Depot Rework Order request.

REASON FOR PORPOSAL

The existing F-2 Foil configuration works well if properly adjusted. However, it is difficult to adjust correctly even if all parts are in good condition. In addition to adjustment difficulties, the pilot has no control to free a stuck record or advance a record should the pawl stick. The proposed changes eliminate, or reduce, the likelyhood of malfunctions that have been experienced with this equipment. These changes will also reduce the maintenance required to keep these units operational.